

CASE HISTORY RENAULT LAGUNA

VEHICLE FAULTS:- Cutting out when pulling away in first gear

VEHICLE HISTORY:-The customer had previously had the car checked out and various components had been replaced, there were no fault codes stored and engine management live data was normal when checked statically.

TESTING:-Static checks only revealed poor plug leads so testing in our rolling road was carried out. The fault was traced to a break in the main engine harness; repair of the corroded loom section cured the fault.



Broken corroded wiring loom causing cutting out

CONCLUSION: - Dyno testing is the quickest and most cost effective route to find faults under load .

