

## CATALYST QUALITY COMPARISON OF AFTERMARKET AND GENUINE

We are increasingly seeing problems with replacement aftermarket catalyst as shown below there is often a significant reduction in the size of the aftermarket catalyst which whilst reducing the cost also reduces the efficiency and lifespan of the product . With modern vehicles the catalyst is monitored by the engine management system and we have seen a number of cases where the aftermarket catalyst whilst reducing the c.o. content to pass an MOT will not work efficiently over all operating conditions and the engine management warning light will come on with a stored fault for catalyst efficiency.



Comparison of aftermarket and genuine catalyst VW Golf